

POINT CHECKED (-Z- AXIS) NEEDS TO ADD .01917 FROBE RADIUS.

No.

, i

No. 2

22	MEASURE		.) 60242
	X-Coordinate	0.25577	> POINT
	Y-Coordinate	-0.40801	
:::-	Z-Coordinate	0.32367	

No. 3

23	MEASURE		\ DOINT
	X-Coordinate	0.31682	> POINT
	Y-Coordinate	-0.04971	
	1-Coordinate	0.35488	

No. 4

24	MEASURE		> FOINT
	X-Coordinate	1.42660	7 101111
	Y-Coordinate	0.19321	
	2-Coordinate	0.64826	

No. 5

25	MEASURE		> POINT
	X-Coordinate	1.42643	/ FUINI
	Y-Coordinate	-0.24002	
	Z-Coordinate	0.64488	

No. A

. 26	MEASURE) parms
	X-Coordinate	1,42585	> POINT
		1,42383	
	· Y-Coordinate	-0.60846	
	7-Coordinate	AFRFA. Ø	

Part Prg. # 000 Date: Mon Dec 08 : Page 4 Time: 14:49:55 ELEMENT : MEASUREMENT : NOMINAL : DEVIATION : TOLERANCE ACTUAL : FERCENTAGE OF TOLERANCE USED VALUE : ; VALUE : 1 RANGE - 1 : 1 100 50 0 50 100 No. 7 ŗ ŗ 27 MEASURE ----> POINT X-Coordinate 2.51796 Y-Coordinate -0.13600 **I-Coordinate** 0.51032 No. 8 *55.15* · 28 MEASURE ----> POINT X-Coordinate 2.45738 Y-Coordinate -0.50791 I-Coordinate 0.51987 No. 9 29 MEASURE ----> FOINT X-Coordinate 2.45138 Y-Coordinate -0.90479 2-Coordinate 0.51366 1 1 No. 10 30 MEASURE ----> POINT X-Coordinate 3.30732 Y-Coordinate -0.79157 **Z-Coordinate** 0.12274

No. 11

31 MEASURE ----> FOINT X-Coordinate 3.06898 Y-Coordinate -1.35673 Z-Coordinate 0.25111

No. 12

32 MEASURE ----> FOINT X-Coordinate 2.88721 Y-Coordinate -1.82804 Z-Coordinate 0.32459

33 MEASURE X-Coordinate ----> POINT 3.55407 Y-Coordinate -1.87876 1-Coordinate -0.09626 ç No. 14 34 MEASURE X-Coordinate ----> POINT 3.04127 Y-Coordinate -2.54722 1-Coordinate 0.21705 . . . Part Pro. # 000 Page 5 Date: Mon Dec 08 200 Time: 14:49:55 NOMINAL : DEVIATION : 1 : TOLERANCE FERCENTAGE OF TOLERANCE USED - 1 VALUE : VALUE : RANGE ; 35 MEASURE ----> POINT X-Coordinate 3.28070 Y-Coordinate -3.28184 1-Coordinate 0.03313 No. 16 36 MEASURE X-Coordinate ----> POINT 2.64113 Y-Coordinate -3.34156 2-Coordinate 0.35334 No. 17 MEASURE

----> POINT

No. IR

X-Coordinate

Y-Coordinate

1-Coordinate

2.35835

-2.73214

0.46852

37

38	MEASURE X-Coordinate Y-Coordinate Z-Coordinate	1.65221 -3.18597 0.55964	> p	'01#T
39	MEASURE X-Coordinate Y-Coordinate Z-Coordinate	2.22486 -3.73500 0.44891	> FI	THIC
	Ma 199			

40	MEASURE X-Coordinate Y-Coordinate I-Coordinate	3.29366 -3.31832 0.02149)	POINT
----	---	--------------------------------	---------------	-------

No. 21
HU: 21

41	MEASURE X-Coordinate Y-Coordinate Z-Coordinate	2.87489 -4.12237	>	POINT
	- 0001011865	0.20290		

No. 22

42	MEASURE		1
	X-Coordinate	1.50494	> POINT
	Y-Coordinate	-4.30583	
	Z-Coordinate	0.53379	